BUILDING SAFETY CERTIFICATE

No:112/09/06/2022

Dated: 09/06/2022

It is certified that the existing building Christ CMI Public School at Ooty Road, Gundlupete Taluk, Chamarajanagar Distrist is having 1 block, Ground floor + 2 floors as per details below

Details of Block (s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No of Floor (s) In the Block	3 Floors					

The Building is owned/occupied by Christ CMI Public School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Working Department No-2 on 06/06/2022 in the presence of Mathew Jose, Secretary of Christ CMI Public School, Gndlupete and that the building/premises is fit for occupancy for running school with effect from 09/06/2022 for a period of 5 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. Ramp and railing provided for physically handicapped Students
- 2. Stair case width is 1.85 mtrs, Rise of step is 0.15 mtrs, tread is 0.30 mtrs
- 3. Ceiling Height from floor measured and it is 3.58. mtrs

4. Paved roads, available for the movement of fire engine all round building O

Strike out whichever is not applicable.

Issued on 09/09/2022 at Gundlupete By PWD Department

Name :Ramachandra

Designation: Assistant Executive Engineer

Name & Address of Department/Office: Public Working Department No. 2

Sub Division, Gundlupete

1

CHAMARAJANAGARA DIST. (KARNATAKA)



ಲೋಕೋಪಯೋಗಿ ಬಂದರು ಮತ್ತು ಒಳನಾಡು ಜಲಸಾರಿಗೆ ಇಲಾಖೆ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಛೇರಿ, ನಂ.2ನೇ ಉಪ–ವಿಭಾಗ, ಗುಂಡ್ಲುಪೇಟೆ.

ಸಂಖ್ಯೆ:ಸ.ಕಾ.ಅ.ನಂ.2.ಲೋ.ಇ.ಉ.ವಿ.ಗುಂ.ಪೇ/ಇತರೆ/2019-20.(೧५८)
281(2020

ಮುಖ್ಯೋಪಾಧ್ಯಾಯರು ಕ್ರಿಸ್ಟ್ ಸಿ.ಎಂ.ಐ. ಪಬ್ಲಿಕ್ ಸ್ಕೂಲ್ ಊಟಿ ರಸ್ತೆ, ಗುಂಡ್ಲುಪೇಟೆ-571111.

ಮಾನ್ಯರೆ,

ವಿಷಯ:- ಶಾಲಾ ಕಟ್ಟಡವು ಸುಸ್ಥಿತಿಯಲ್ಲಿರುವ ಧೃಢೀಕರಣ ಪತ್ರ ನೀಡುವ ಬಗ್ಗೆ ಉಲ್ಲೇಖ:- ತಮ್ಮ ಪತ್ರ ದಿನಾಂಕ:-21.01.2020.

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಗುಂಡ್ಲುಪೇಟೆ ಪಟ್ಟಣದ ಮೈಸೂರು ಊಟ ರಸ್ತೆಯಲ್ಲಿರುವ ಕ್ರಿಸ್ಟ್ ಸಿ.ಎಂ.ಐ. ಪಬ್ಲಿಕ್ ಸ್ಕೂಲ್ ಕಟ್ಟಡದ ಸುಸ್ಥಿತಿಯ ಬಗ್ಗೆ ಧೃಢೀಕರಣ ಪತ್ರ ಕೋರಿರುವುದು ಸರಿಯಷ್ಟೆ, ಅದರಂತೆ ಸದರಿ ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ:-22.01.2020 ರಂದು ಈ ಕಛೇರಿಯ ಶ್ರೀ ಎಂ.ಪುರುಷೋತ್ತಮ, ಕಿರಿಯ ಇಂಜಿನಿಯರ್ ರವರು ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿದ್ದು, ಸದರಿ ಕಟ್ಟಡದ ಇಟ್ಟಿಗೆ ಗೋಡೆಗಳಲ್ಲಿ ಸಣ್ಣಮಟ್ಟ ಬಿರುಕುಗಳು ಉಂಟಾಗಿದ್ದು, ಸದರಿ ಬಿರುಕುಗಳನ್ನು ಸರಿಪಡಿಸಿಕೊಂಡಲ್ಲಿ ಉಳಿದಂತೆ ಕಟ್ಟಡವು ಸುಸ್ಥಿತಿಯಲ್ಲಿದ್ದು, ವಿದ್ಯಾಭ್ಯಾಸ ನಡೆಸಲು ಯೋಗ್ಯವಾಗಿದೆ ಎಂದು ಈ ಮೂಲಕ ಧೃಢೀಕರಿಸಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು ಲೋಕೋಪಯೋಗಿ ಬಂದರು ಮತ್ತು ಒಳನಾಡು ಜಲಸಾರಿಗೆ ಇಲಾಖೆ, ನಂ.2ನೇ ಉಪ–ವಿಭಾಗ, ಗುಂಡ್ಲು ಪೇಟೆ.