

BUILDING SAFETY CERTIFICATE

No : 8276

Dated :13/01/2025

It is certified that the existing building Christ CMI Public School at Ooty Road, Gundlupete Taluk, Chamrajanagar district, is having one block, ground floor + 2 floors as per details below

Details of Block (s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No of Floor (s) in the Block	Ground Floor + 2 Floors					

The Building is owned/occupied by Christ CMI Public School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Working Department No-2 on 08/01/2025 in the presence of Mathew Jose, Secretary of Christ CMI Public School, Gundlupete and that the building/premises is fit for occupancy for running school with effect from 13/01/2025 For a period of 5 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Ramp and railing provided for physically handicapped Students
 2. Stair case with is 1.50 mtrs, Rise of step is 0.15 mtrs, tread is 0.30 mtrs
 3. Ceiling Height from floor measured and it is 3.45. mtrs
 4. Paved roads, available for the movement of fire engine all round building
- Stike out whichever is not applicable

Issued on 13/01/2025 at Gundlupete by PWD Department

Signature with Seal :

Name:

Designation :

Name & Address of Department /Office :

Ravi Kumar
Assistant Executive Engineer
Public Works Department
Sub Division - Gundlupete

Ravi Kumar

Assistant Executive Engineer.

P.W.D. Department
No:2, Gundlupete