

To

**Christ CMI Public School
Ooty Road, Gundlupete
Chamarajanagar District -571111**

Annexure C

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No:02/2025

Date : 22/03/2025

It is certified that an inspection team headed by **Smt L Renukadevi, PHCO, HWC, Gundlupete B** (Name of officers with designation) from **HWC ,Gundlupete PHED** inspected the CHRIST CMI PUBLIC SCHOOL , Ooty Road, Gundlupete, Chamarajanagar District on **20/03/2025** (date of Inspection) and on the basis of water test report (Attached) Bearing No **02/2025** dated **20/03/2025** of **Nanekatte (PHED Lab)** certified that the CHRIST CMI PUBLIC SCHOOL, Ooty Road, Gundlupete, Chamarajangara District (Name of School) has safe drinking water facilities for the students and members of the institution. School is also maintain the hygienic sanitation condition in the school building and the campus as per norms prescribed by the Central /State/U.T/Govt.

The certificate valid till **21/09/2025**

Seal and /signature o the office/department

**Signature
Medical Officer**


ವ.ದಾ.ವಕಾಲಿಗಳು
ಪ್ರಾಥಮಿಕ ಆರೋಗ್ಯ ಕೇಂದ್ರ,
ನೀನೇಕಟ್ಟೆ, ಗುಂಡ್ಲುಪೇಟೆ ತಾಲ್ಲೂಕು