



**KARNATAKA GOVT
DEVELOPMENT OF HEALTH AND FAMILY
PRIMARY HEALTH CENTER OF NENEKATTE
GUNDLUPET TALUK, CHAMRAJANAGARA DISTRICT**

WATER TESTING REPORT

Sl No	Location of Sample Collected	Source of Water	Date & Time sample collected	Test Performed	Result	Date result reported
1	Christ CMI Public School Water Purifier Ground Floor, Left Side	Purified Water	20.03.2025 04:15 PM	Hydrogen Sulphide (H ₂ S) Method	Water Sample does NOT Show coliform bacterial contamination.	22.03.2025
2.	Christ CMI Public School Water Purifier Ground Floor, Right Side	Purified Water	20.03.2025 04:17 PM	Hydrogen Sulphide (H ₂ S) Method	Water Sample does NOT Show coliform bacterial contamination.	22.03.2025
3.	Christ CMI Public School Overhead Water Tank Top Floor.	Bore Well	20.03.2025 04:25 PM	Hydrogen Sulphide (H ₂ S) Method	Water Sample Does NOT Show coliform bacterial contamination.	22.03.2025

NOTE:

1. Hydrogen sulphide (H₂S) test is for testing contamination of drinking water dacteria of faecal origin. Only microbial quality of drinking water is tested and reported. No other parameter has been tested.
2. Laboratory tests are limited by the sensitivity and specificity of the assay procedure and also the quality of the sample submitted.
3. Repeat testing of water of at least once in 3 months is recommended.
4. Partial reproduction of this report is not permitted.

Sample submitte by:

Smt. L Renukadevi
PHCO. HWC Gundlupet B


Reported by:

Mr. Mahadevaswamy LTO
GH Gundlupet

Signature
Medical Lab Technical Officer

Signature
Medical Officer

Medical officer
Primary health center
Nenekatte, Gundlupete
Chamarajangara



C.P. Nagamallappa
C.P. Nagamallappa. B.Com. LL.B.
Advocate
Notary (Govt. of India)
GUNDLUPET-571 111

20/3/2025



ಕರ್ನಾಟಕ ಸರ್ಕಾರ
ಆರೋಗ್ಯ ಮತ್ತು ಕುಟುಂಬ ಕಲ್ಯಾಣ ಇಲಾಖೆ
ಪ್ರಾಥಮಿಕ ಆರೋಗ್ಯ ಕೇಂದ್ರ ನೇನೇಕಟ್ಟೆ
ಗುಂಡ್ಲುಪೇಟೆ ತಾಲ್ಲೂಕು, ಚಾಮರಾಜನಗರ ಜಿಲ್ಲೆ



WATER TESTING REPORT

SI NO	Location of Sample Collected	Source of water	Date & Time sample collected	Test Performed	Result	Date result reported
1	Christ CMI Public School Water Purifier Ground Floor, Left Side	Purified Water	20.03.2025 04:15 PM	Hydrogen sulphide (H ₂ S) Method	Water Sample does NOT show coliform bacterial contamination.	22.03.2025
2	Christ CMI Public School Water Purifier Ground Floor, Right Side	Purified Water	20.03.2025 04:17 PM	Hydrogen sulphide (H ₂ S) Method	Water Sample does NOT show coliform bacterial contamination.	22.03.2025
3	Christ CMI Public School Overhead Water Tank Top Floor	Bore well	20.03.2025 04:25 PM	Hydrogen sulphide (H ₂ S) Method	Water Sample does NOT show coliform bacterial contamination.	22.03.2025

NOTE:

1. Hydrogen sulphide (H₂S) test is for testing contamination of drinking water with bacteria of faecal origin. Thus, only microbial quality of drinking water is tested and reported. No other parameter has been tested.
2. Laboratory tests are limited by the sensitivity and specificity of the assay procedure and also the quality of the sample submitted.
3. Repeat testing of water of at least once in 3 months is recommended.
4. Partial reproduction of this report is not permitted.

Sample submitted by:

Smt L Renukadevi
PHCO, HWC Gundlupet B

Reported by:

Mr Mahadevswamy, LTO
GH Gundlupet

Signature
Medical Lab Technical Officer

Signature
Medical Officer
ವೈದ್ಯಾಧಿಕಾರಿಗಳು

End of report

ಪ್ರಾಥಮಿಕ ಆರೋಗ್ಯ ಕೇಂದ್ರ
ನೇನೇಕಟ್ಟೆ, ಗುಂಡ್ಲುಪೇಟೆ ತಾಲ್ಲೂಕು